

# Release Notes

**EAP1300**

**Ver. v3.6.5\_c1.9.30**

## Revision History

Revision	Date	Reason of Changes
v3.6.5_c1.9.30	Sep 26, 2019	Change and Fix update

## Change Log

F/W Version	v3.6.5_c1.9.30
Type	Description
New Feature	N/A
Change	<ol style="list-style-type: none"><li>1. Support Mesh in standalone mode.</li><li>2. Management SSID will be off in controller mode.</li><li>3. Add a popup window to remind user change the default login credentials after first login.</li><li>4. Modify traffic log from 100/s to 10/s to fix kernel panic issue.</li></ol>
Fix	<ol style="list-style-type: none"><li>1. Fixed VoIP issue in WDS Bridge mode.</li><li>2. Fix ping high latency issue.</li><li>3. Fix fingerprint does not work issue.</li><li>4. Fix Chrome IOT issue.</li></ol>