



Release Notes

# SkyKey I

## v1.0.67S\_c1.9.67

10<sup>th</sup> September, 2021

This document provides release information for SkyKey I

## Table of contents

<b>Introduction</b>	<b>3</b>
<b>What's New</b>	<b>4</b>
<b>Supported Platforms</b>	<b>5</b>
<b>Legacy Devices</b>	<b>6</b>
<b>Upgrade Information</b>	<b>7</b>
<b>Limitation</b>	<b>7</b>
<b>Fixed Bugs</b>	<b>7</b>

## Introduction

The v1.0.67S will be included bugs fixed issues on SkyKey I.

## What's New?

**N/A**

To ensure compliance with SkyKeyl v1.0.67S on new functions including WPA3, bit rate control and Enable/Disable 11ax under 2.4GHz radio, the Access Point f/w should be upgraded to the v3.7.0 or the later version. The legacy models will not be supported the new function.

-----Worked with v1.0.67S, FW version should be upgrade to v3.7.0 or the later version. -----

- **Indoor**

- EWS330AP
- EWS355AP
- EWS357AP (v1/v2/v3)
- EWS377AP (v1/v2/v3)
- EWS385AP
- EWS550AP
- EWS850AP
- EAP1250
- EAP1300(EXT)

- **Outdoor**

- ENS500-ACv2
- ENS500EXT-ACv2
- EnStation5-ACv2
- EnStationACv2
- ENS620EXT
- ENH1350EXT

-----Worked with v1.0.65S, without supporting any new functions for the version.-----

- **Switches**

- EWS2908P
- EWS2910P(v2)
- EWS5912FP
- EWS7928P
- EWS1200-28TFP
- EWS7952P
- EWS7952FP
- ECS1008P
- ECS1112FP
- ECS1528FP
- ECS1552FP

## Legacy Devices

The following devices can be compatible with v1.0.61S, but not supporting new functions.

- EWS300AP
- EWS310AP
- EWS350AP
- EWS360AP
- EWS370AP
- EWS371AP
- EWS500AP
- EWS510AP
- EWS511AP
- EAP1750H
- EAP2200
- ENS500-AC
- ENS500EXT-AC
- EnStation5-AC
- EnStationAC
- ENS610EXT-NVK
- ENH1750EXT
- EWS650AP
- EWS660AP
- EWS860AP
- EWS870AP
- EWS871AP
- ENS202EXTv2

## Upgrade Information

- **N/A**

## Limitation

- **N/A**

## Fixed bugs

- Modify the password of Admin Account disallow the dollar sign ( \$ ).
- OCU firmware download failed of the EnStation5\_ACv2.
- Bulk upgrade failed for upload 93xx switch.
- When AP is offline, the active client list will not update.
- Client log and event log are cleared every day.

## Known Issues

- **N/A**

**Costa Mesa, California, USA** | (+1) 714 432 8668

[www.engeniustech.com](http://www.engeniustech.com)

**Markham, Ontario , Canada** | (+1) 905 940-8181

[www.engeniustech.com](http://www.engeniustech.com)

**Dubai, UAE** | (+971) 4 357 5599

[www.engenius-me.com](http://www.engenius-me.com)

**Singapore** | (+65) 6227 1088

[www.engeniustech.com.sg](http://www.engeniustech.com.sg)

**Eindhoven, Netherlands** | (+31) 40 8200 888

[www.engeniusnetworks.eu](http://www.engeniusnetworks.eu)

**EnGenius®**

Features and specifications subject to change without notice. Trademarks and registered trademarks are the property of their respective owners. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference in which case the user will be required to correct the interference at his/her own expense. Prior to installing any surveillance equipment, it is your responsibility to ensure the installation is in compliance with local, state and federal video and audio surveillance and privacy laws.