

Release Notes

EAP1300

Ver. v3.6.6_c1.9.30

Revision History

Revision	Date	Reason of Changes
v3.6.6_c1.9.30	Nov 8, 2019	Change and Fix update

Change Log

F/W Version	v3.6.6_c1.9.30
Type	Description
New Feature	N/A
Change	1. Support SENA0 Post-Association band steering algorithm.
Fix	1. Fixed captive portal session timeout issue. 2. Fixed bridge error when using captive portal and enable the management VLAN.