

# **Release Notes**

**EWS860AP**

**Ver. v3.0.7\_c1.8.59**

## Revision History

| Revision       | Date         | Reason of Changes |
|----------------|--------------|-------------------|
| v3.0.7_c1.8.59 | Nov 15, 2017 | Fix update        |
|                |              |                   |

## Change Log

**Notice:** APs upgraded to this version can only be managed by ezMaster/EWS Switch running c1.8 software.

|             |   |
|-------------|---|
| F/W Version | v3.0.7_c1.8.59  |
| Type        | Description   |
| New Feature | N/A   |
| Change      | N/A   |
| Fix         | 1. Fix the issue that guest network become abnormal upon last hot fix update. |