

# Release Notes

**EWS1200-28TFPv2**

**Ver. v1.07.43\_c1.9.37**

## Revision History

| Revision         | Date         | Reason of Changes |
|------------------|--------------|-------------------|
| v1.07.43_c1.9.37 | Mar 22, 2021 | Fix update        |
|                  |              |                   |

## Change Log

**Notice:** Must upgrade the ezMaster to v1.0.64\_c1.9.62.

|             |  |
|-------------|--|
| F/W Version | v1.07.43_c1.9.37   |
| Type        | Description  |
| New Feature | N/A  |
| Change      | N/A  |
| Fix         | 1. Fix the issue that the connected port cannot display correctly in topology view when the ECS switch and EWS switch are in the same network. |